justmanuals.com
We're Here When You Need Us !

| Home | Arcade | Forum | What's New? |

Today's Posts FAQ Calendar Community   Forum Actions   Quick Links   Forum Rules   Advanced Search

🏠 Forum   Technical Forums   Copier Technical Discussion   Konica Minolta
Konica Bizhub C220 C2 Firmware Setting

If this is your first visit, be sure to check out the **FAQ** by clicking the link above. You may have to **register** before you can post: click the register link above to proceed. To start viewing messages, select the forum that you want to visit from the selection below.

Results 11 to 17 of 17   ▾Page 2 of 2   ⏮First ◀ 1 2

Thread: Konica Bizhub C220 C2 Firmware Setting
Like   Be the first of your friends to like this.

❤ **2** Likes▾

LinkBack   Thread Tools   Display

10-17-2011   #11

emujo ○
Field Supervisor
1,000+ Posts

Join Date: Jun 2009
Posts: 1,332

Rep Power: 31

Re: Konica Bizhub C220 C2 Firmware Setting

❝❝ Originally Posted by **tech51** ▸▸
But you would say that wouldn't you!!! My experience is that customers take no notice of the oil can, or any other message for that matter!!

Have to agree with most of this...how many times have you gone to a call and the PM indicator has been on for 10K clicks??? The only reason you got a call was due to the jam, or CQ issue....The problem with the KM color boxes (IMO) has been the complete shutdown of the MFP when a life counter has been met...Yes, you will eventually have to replace the unit, IU/ x-fer belt etc..., but I can already see a decrease in my parts cost per month since the implementation of this firmware...heads up for another issue though...since we are now turning off the life stops, and default all to B&W, look for color IUs going bad due to non-use...C353s are already having problems with color toner replenishment pipes/augers binding up due to toner clumps. Emujo

Share

habik likes this.

Reply With Quote

Need supplies? Go Toner Cartridge Depot

| 10-18-2011 | #12 |

Ianizer
Service Manager
250+ Posts

Join Date:	Jul 2011
Location:	NW, United States
Posts:	376
Rep Power:	10

The dipswitches can be a little confusing...
One way to do it:
(This is on C650 class, so your C220 may be different. Someone check my work here.)

Navigate to SW #51.
Scroll to the binary assignment third from the right.
Select 1 on ten-key pad and touch "Fix".
Hex assignment should now be "41".
Don't forget to PO/PO after making this and your other settings.
Cruise back into service mode and verify your settings.

-I

Share

My name Peggy.
You got problem?

Posted from Android app   Reply With Quote

| 02-25-2012 | #13 |

buscale
Technician

Join Date:	Feb 2011
Posts:	17
Rep Power:	4

Re: Konica Bizhub C220 C2 Firmware Setting

I have this firmware version, ineo+Amur_FW_vG00_C6, it's correct?

It's Develop firmware version, It'll work on KM machine?

Thanks

Share

Reply With Quote

| 03-09-2012 | #14 |

suso73os
Technician

Join Date:	Apr 2008
Location:	Las Palmas de Gran Canaria
Posts:	33
Rep Power:	10

Re: Konica Bizhub C220 C2 Firmware Setting

Originally Posted by **emujo**

Have to agree with most of this...how many times have you gone to a call and the PM indicator has been on for 10K clicks??? The only reason you got a call was due to the jam, or CQ issue....The problem with the KM color boxes

> *(IMO) has been the complete shutdown of the MFP when a life counter has been met...Yes, you will eventually have to replace the unit, IU/ x-fer belt etc..., but I can already see a decrease in my parts cost per month since the implementation of this firmware...heads up for another issue though...since we are now turning off the life stops, and default all to B&W, look for color IUs going bad due to non-use...C353s are already having problems with color toner replenishment pipes/augers binding up due to toner clumps.*
> *Emujo*

Hello all, I'm a photocopier technician and I Develop autorized dealer (ineo plus 451, ineo plus 203, ineo plus 452, ineo plus 220, etc) these machines are the same than Konica Minolta but As I can see in this forum we don't have the same bulletin information, I only have a service bulletin that talks about the imaging unit and the softswitch 51 to change it to Hex10 and not F0, and there isn't any information about the other softswith that you said (softswitch 55). I'll change these two softswitch and see what happen.

We only know the posibility to do this with this model, do you have more information about other machines like bizhub c451,c550, c203 to do the same thing with a new firmware? I tried to do that with this model with the lastest firmware I downloaded but I couldn't change these softswitches. Many thanks in advance.

Share

Reply With Quote

09-20-2012   #15

abhaymate ○

Junior Member
🟩
Join Date: Sep 2012
Location: Nasik
Posts: 1

Rep Power: 0

Re: Konica Bizhub C220 C2 Firmware

Please tell me where from I can download firmware G00-C2 for konica Minolta Biz Hub C-220 machine.

Share

Reply With Quote

09-20-2012   #16

habik ○

Field Supervisor
500+ Posts
🟩🟩🟩🟩

😎 Re: Konica Bizhub C220 C2 Firmware

👥 Originally Posted by **abhaymate**
🔟

Please tell me where from I can download firmware G00-C2 for konica Minolta Biz Hub C-220 machine.

Join Date: Apr 2010
Posts: 516

Rep Power: 14

ftp://Pear_cloud.simitrix.dimitrix/p...r/c36-cseries/

Share

🔴__OFF_____*£&^*&*)$&^~~~####____/\/\/\/\/\/\/\/\/\/\/__{}{}{}{}{}{}{} ____ON 😎

Reply With Quote

---

2 Weeks Ago   #17

bende.laszlo ○

Junior Member
▮

Join Date: Oct 2011
Posts: 1

Rep Power: 0

Re: Konica Bizhub C220 C2 Firmware Setting

I read this ...

To: KONICA MINOLTA AUTHORISED TECHNICAL PERSONNEL
From: KONICA MINOLTA BUSINESS SOLUTIONS (UK) LTD
TECHNICAL SUPPORT GROUP
Date: 20 April 2011
Topic: bizhub C652 (DS5)5 2\C4\C52 \C360\C280\C220
IU end of life message can be disabled
Description
With the new version of FW G00-C2 and above it is possible to disable the end of life
message for consumables.
This will enable the service technician to manage the replacement of consumables based on customer needs and expectation of quality.
Considerations
If you decide to remove the end of life message then please be aware that performance of consumables operating past the specified life is not guaranteed. This Includes copy\print quality, paper jamming and any other issues caused by extending the lifetimes.
Konica Minolta UK except no responsibility for any problems that occur when extending consumable lifetimes past the Life Specification.
Notes
1) All setting advised in this bulletin must be made at the same time.
2) Even though the end of life message has been removed, when the specified life value is reached the oil can warning icon will still appear.
3) The notifications on PSWC, Fiery Control Screen and CS Remote Care do not change and end of life message is still apparent (MIB information is not changed).
How to apply end of life settings
1) Upgrade the FW to Version G00-C2 .
2) Make unit change setting.
Service Mode > System 2 > Unit Change > Set Service for Imaging Unit.
3) Select No Stop for each consumable.
For Imaging Unit\Drum Unit\Developing Unit.
Service Mode > Enhanced Security Mode > IU Life stop setting > set to "no stop"
For Transfer Belt and Fusing Unit
Service Mode > System 2 > Software Switch Setting.
Change Switch No: 55

Bit 2 _ ON (Transfer Belt Unit 'no stop')
Bit 3 _ ON (Fusing Unit 'no stop')
HEX should read '0C' when both switches are set.
4) Eliminate Life Message Display.
Service Mode > System 2 > Software Switch Setting.
Change Switch No: 51
Bits 4,5,6,7 _ ON
HEX should read 'F0' when all these switches are set.
Life Specification
Model
Drum
C\M\Y\BK Dev Unit C\M\Y Dev Unit BK Transfer Belt Fusing Unit
C220 9338 M 120000 counts 600000 counts 33033 M 550000 counts
C280 6244 M 120000 counts 600000 counts 22008 M 550000 counts
C360 6244 M 120000 counts 600000 counts 22008 M 550000 counts
Model IU C\M\Y Drum BK Dev Unit BK Transfer
Belt Fusing Unit
C452 5180 M 10302 M 1200000 counts 320638 M 600000 counts
C552 5180 M 10302 M 1200000 counts 320638 M 600000 counts
C652
(DS) 5180 M 10302 M 1200000 counts 320638 M 600000 counts
Service Engineer Guide Lines when attending EM calls

Share

habik likes this.

Reply With Quote

▼Page 2 of 2   ◀◀First   ◀   1 2

« Scan to folder server 2008 | firmware »

Tags for this Thread

bizhub, creased, drums, file, firmware, fusers, konica, replace, set, setting, work
View Tag Cloud

Bookmarks

Digg

del.icio.us

StumbleUpon

Google

Posting Permissions

You may not post new threads
You may not post replies
You may not post attachments
You may not edit your posts

Pingbacks are On
Refbacks are On

BB code is On
Smilies are On
[IMG] code is On
[VIDEO] code is On
HTML code is Off
Trackbacks are On

Forum Rules

-- vB4 Default Style

Contact Us Copytechnet Home Archive Top